



Jan 2 1891
I commenced a Survey of Section 6, T. 8, R. 6
for Hugo Fox et al.
Locate Lot.

This survey by consent of all parties
in section and all parties helped.

C. B.

Henry Edmund
Surveyor Greene County.

Var.

Course.	Point of Beginning.	Chains Distance.	Corrected Bearings.
North	SE	78.10	to N.W.
West	SE	79.49	to S.W.
North	SW	79.00	to N.W.
West	NE	79.04	to N.W.

This cor located by lines South from E 1/4 Sec 31 9-6

CORNER ESTABLISHED.	Monument.	Device.	WITNESS POINTS OR BEARING TREES.	Mark or Dia. in Inches.	COURSE.	Links Distant.	REMARKS.
Sec 1/4 NE	Concret Block		Burr Oak	30"	N 68° E	244	
Cor SW	Limestone		" "	8"	S 35° E	14	
Cor SE	"		" "	5"	S 50° E	8	
W 1/4 SE 1/4	"		" "	24	N 8 1/2° W	59	
Cor 1/4	"		Hickory	8"	N 56° W	8 1/2	
S 1/4 SW	Iron Pin		Burr Oak	12"	S 73° 25' E	83 3/4	
S 1/4	"		Stone		North	25	
S 1/4 SE	Limestone		No witness.				
N 1/4 SE	Concret Block		No witness.				
E 1/4 NE	Stone		Stonemason		South	140 1/2	
N 1/4	Iron Rod		Stone 21 links		South	46 links	South.
N 1/4 NE	Concret Block		No witness				
N 1/4	1st tile piece		with small piece around them.				
W 1/4 NE 1/4	S clay tile		pieces with pieces like				
W 1/4	"		Burr Oak	6"	S 6 1/2° W	20	
W 1/4	Limestone		Silver Poplar	24"	N W.	81	16 ft W of the road.
N W	"		SW cor W Head culvert			18 ft	
			SE .. E ..			16.6 ft.	
N 1/4 NW	Iron bar 1" sq.		No witness				
Cor NW	Limestone		No wit.				
S 1/4 NW	"		No Wit.				
W 1/4 SW	Iron Bar 1" sq.		No Wit				center road.
W 1/4 NW	Sand Stone		at 20' east of west line (center road)				